

# EASZ-TG11 ULTRASONIC THICKNESS GAGE USER'S MANUAL



**Version V1.0 NA** 

## <u>IMPORTANT</u>

#### **WARNING**

Please read this manual entirely before attempting to operate the EASZ-TG11. Improper use can lead to incorrect results and damage to the gage.

All statements, technical information and recommendations contained in this manual are based on tests we believe to be reliable, but the accuracy or completeness thereof is not guaranteed. Before using the product you should determine its suitability for your intended use. The end user bears all risk in connection with the use of this product.

You are reminded that all warranties as to merchantability and fitness for purpose are excluded from the contract under which the product has been supplied to you. The seller's only obligation in this respect is to replace such quantity of the product proved to be defective.

NEITHER THE SELLER NOR THE MANUFACTURER SHALL BE LIABLE EITHER IN CONTRACT OR TORT FOR DIRECT OR INDIRECT LOSS OR DAMAGE (WHETHER FOR LOSS OR PROFIT OR OTHERWISE), COSTS, EXPENSES OR OTHER CLAIMS FOR CONSEQUENTIAL OR INDIRECT COMPENSATION WHATSOEVER (AND WHETHER CAUSED BY THE NEGLIGENCE OF EESIFLO, ITS EMPLOYEES OR AGENTS OR OTHERWISE).

## **Table of Contents**

INTRODUCTION	1
How the TG11 Works	
AREAS of APPLICATION	
PARTS and CONTROLS	
UNITS OF SONIC VELOCITY	4
SWITCHING BETWEEN METRIC AND IMPERIAL	
SWITCHING BETWEEN METRIC AND IMPERIAL	4
CALIBRATION	
Calibration for Mild Steel	
Calibration with Known Sonic Velocities	5
Calibration with Unknown Sonic Velocities	6
THICKNESS MEASUREMENT TECHNIQUES	6
Ensure Surfaces are Clean	
Apply Acoustic Couplant	
Cross-Talk Barrier	
Rough or Grooved Surfaces	
Measuring on Cylinders	
Measuring on Non-Parallel Surfaces	
The Effects on Materials & Temperature	
Typical Sonic Velocity Table	9
Battery Care and Use	
Precautions	10
FASZ-TG11 Specifications	11

## INTRODUCTION

The EASZ-TG11 is a hand held microcontroller based ultrasonic thickness gage. It operates on two AA batteries and is very easy to use.

Please read this manual and follow the instructions carefully to get the best results from your instrument.

## **How the TG11 Works**


The EASZ-TG11 Thickness Gage is a "TRANSIT TIME MEASURING DEVICE" which works on the "pulse-echo" principle.

A burst of ultrasonic energy is generated by a piezo-electric crystal contained on one side of the transducer.

This burst of sound travels from the Transmit transducer, past the "Cross Talk Barrier" through a layer of ultrasonic couplant and is transmitted into the material being measured.

The pulse then travels through the material being measured until it reaches a material of a substantially different acoustic characteristic (e.g. air or liquid) which then acts as a transmission barrier, reflecting a portion of the energy back to the Receive transducer located on the opposite side of the Cross Talk Barrier.

The time required by this burst to make a round trip through the material is accurately measured by the highly stable timing electronics found within the TG11, which then determines the thickness of the material by simply multiplying the Sonic Velocity of that material by the measured Transit Time then dividing the results by 2.



#### **AREAS of APPLICATION**

Any metal, plastic, glass, ceramic or any material which satisfactorily conducts ultrasonic signals, having parallel (or concentric) surfaces can be measured for the thickness. A major application for the TG11 is for assessing wall thinning due to corrosion or erosion.

#### Typical applications include

Heat Exchangers Ships Hulls / Decking

Tubing and Pipes Airframes / Wings

Pressure Vessels Plates / Slabs

Castings Billets / Bars

Forgings Plastic Sheets / Pipes

Boilers Rolls

Glass Plates Machined Parts


Axles / Wheels / Rails Extrusions

Storage Tanks Bridges

Steam Lines Flanges



### PARTS and CONTROLS



1 - LCD

4 digits indicating readings, battery and probe coupling status indicators and sonic velocity.

#### 2 - PROBE COUPLING INDICATOR

Changes to a colon symbol when the probe is NOT acoustically coupled to the material being measured.

#### 3 - KEYBOARD

Tactile keyboard containing the 5 operation keys.

#### 4 - POWER

Switches the EASZ-TG11 ON and OFF.

#### 5 - PROBE

For probe recognition and zero adjustment.

#### 6 - CAL Key

Used for calibration of known and unknown materials.

#### 7 - Scroll UP and Scroll DOWN keys

Used during calibration process to increase or decrease values.

#### 8 - CALIBRATION BLOCK

Used for probe recognition and zero adjustment.  ${\bf 3}$ 

## UNITS OF SONIC VELOCITY

This is an important concept which must be understood before operating in the "Imperial Mode".

The TG11 has a 4 digit LCD capable of displaying values between 0000 and 9999.

In the "Metric Mode", Sonic Velocities can be displayed in meters per second between 1000 and 9999 m/sec.

In the "Imperial Mode", Sonic Velocities are displayed in Inches per Second divided by 100.

For example, the Sonic Velocity of Mild Steel is 5920 meters per second or (5920 / 0.0254=) 233,070 inches per second. To accommodate this 6 digit figure, divide the value by 100, and the resulting value of 2330 should be used for the Sonic Velocity in the Imperial Mode. A table at the back of this manual indicates Sonic Velocities of some typical materials in both Metric and Imperial values.

## **SWITCHING BETWEEN METRIC AND IMPERIAL**

- 1. Switch the TG-11 **OFF**.
- Press and hold down the **UP** scroll key.
- 3. Switch the TG11 **ON** by pressing the **POWER** key.
- The decimal point will flash from LEFT to RIGHT on the LCD screen.
- Release the **UP** scroll key and the decimal point will stop moving.
- Press the **UP** scroll key again to move the decimal point to either the **LEFT** or **RIGHT** position as follows:

Left = Imperial (inch) Right = Metric

 Press the **DOWN** scroll key to lock the mode into memory.



## **CALIBRATION**

The calibration process sets up the zero point of the probe and the Sonic Velocity of material being measured as described below.

#### Calibration for Mild Steel

This is the simplest calibration method, setting the probe zero point and adjusting the sonic velocity to that of mild steel (5920 m/sec or 233,000 inches/sec)

#### **Procedure**

- Apply couplant to the calibration block and press the probe firmly against it. When a stable reading is displayed, press the PROBE key.
- After one or two seconds the LCD will display 00.20 inches or 005.0 mm indicating the calibration process is complete.

The TG11 is now ready for use on mild steel.

#### Calibration with Known Sonic Velocities

This method should be employed if you plan on measuring the thickness of anything other than Mild Steel.

#### **Procedure**

- Perform Calibration for Mild Steel as defined above.
- Press "CAL" key twice and the LCD will display 5920 m/sec or 2330 inch/sec, which is the sonic velocity of the mild steel calibration block.
- Remove the probe from the calibration block and use the "UP" or "DOWN" scroll keys to adjust the TG11 to the known sonic velocity of the material you are going to measure. For example, if measurements are being made on copper, adjust the Sonic Velocity to either 1835 inches or 4660 meters.
- ⇒ Don't forget that the displayed values of inches per second are actually inches per second divided by 100

A table of the sonic velocities of the most common materials is located in the back of this manual.

The TG11 is now ready for use on new material.

#### Calibration with Unknown Sonic Velocities

This process should only be used if the Sonic Velocity of the material being measured is unknown, but the thickness of the material is known.

#### **Procedure**

- Perform "Calibration for Mild Steel" as detailed above.
- Apply Acoustic Coupling Compound to the material being measured and couple probe firmly to it.
- When a stable reading is displayed on LCD Remove the Probe.
- Press CAL key until the colon symbol disappears.
- Use the UP or DOWN scroll keys to adjust the displayed reading to the actual thickness of the material being measured.
- Now Couple the Probe to the material being measured.
- The LCD should display **Actual Thickness** of the material being measured.

**Note:** If the probe has been changed, recalibration will be required.

Calibration settings are retained within the TG11.

If the instrument is not used for long period of time it is advised to re-calibrate the gage.

#### THICKNESS MEASUREMENT TECHNIQUES



#### Ensure Surfaces are Clean


Prior to attempting to measure the thickness of any material, always remove any dirt, loose scale, corrosion, particles, flaking paint or other foreign substance from the material surface.

### **Apply Acoustic Couplant**

For smooth surfaces a suitable acoustic couplant is machine oil or even water. For rough surfaces or high temperature applications, a high viscosity couplant such as EESiFlo's Acoustic Coupling Compound is recommended.

#### Cross-Talk Barrier

If you look inside the end of the transducer you will notice a thin metal barrier called the Cross-Talk Barrier running through the center of the transducer, stopping the transmit and receive elements from talking directly to one another.



### Rough or Grooved Surfaces


For very rough or grooved surfaces a highly viscous acoustic couplant such as that provided with the TG11, is recommended.

With a grooved surface, couple the probe to the surface being measured so the probe Cross-Talk Barrier is at right angles to the direction of the grooves.

## Measuring on Cylinders

On cylindrical surfaces probe normality and probe cross-talk orientation is important.

To determine normality, rock the coupled probe back and forth along the curved surface direction on the material surface and use the minimum thickness reading, as this represents probe normality.



Selection of probe cross talk barrier orientation depends on the material surface diameter. On large surface diameter, orient the probe so that its barrier is perpendicular to the cylindrical axis of the material. On smaller diameter, initially orient the probe barrier both perpendicular to and parallel with material cylindrical axis and then use the direction that gives smaller thickness.

#### <u>Measuring on Non-Parallel Surfaces</u>

The surface on either side of a section must be relatively parallel or concentric in order to obtain a satisfactory ultrasound echo for a thickness reading. Non parallel or tapered surface will yield either less accurate or possibly no reading at all

#### The Effects on Materials & Temperature

Both dimensions and sound velocity change with temperature, which in turn affects calibration. Normally, the effect can be ignored for the modest changes in ambient temperature but it is always a good practice to re-calibrate when a noticeable change in ambient temperature occurs.

The situation becomes even more complex when the material temperature is considerable different than ambient. One solution is to calibrate on a reference sample at same temperature as the material. Another solution is to calibrate on a reference sample at ambient temperature and then add an experimentally derived correction factor for the temperature of the material.



## **Typical Sonic Velocity Table**

Approximate Sonic Velocity values for a variety of common Industrial materials.

Materials	Sonic Velocity (inch/sec)/100	Sonic Velocity (m/sec)
Acrylic Resin	1051	2670
Aluminium	2488	6320
Brass, Naval	1744	4430
Bronze,	1390	3530
Cast Iron	1811	4600
Copper	1835	4660
Glass, Window	2673	6790
Inconel	2252	5720
Iron	2323	5900
Magnesium	2484	6310
Monel	2370	6020
Nickel	2217	5630
PE	921	2340
PVC	945	2400
Quartz Glass	2193	5570
Steel Casting	2303	5850
Steel, Mild	2330	5920
Steel, 4330	2303	5850
Steel, 303	2228	5660
Titanium	2390	6070
Zinc	1642	4170
Zirconium	1831	4650

## **BATTERY CARE and USE**

Low Battery indication is provided by the LCD blinking for up to ½ hour. Charge or replace batteries.

The TG11 operates on any AA type dry, alkaline, or Ni-Cd batteries. When using Ni-Cd batteries, the batteries should be charged prior to being used.

#### **Precautions**

- Avoid shock to instrument or probe.
- Wipe the couplant off the probe and calibration block after use.
- Plug and unplug cables with care. Check polarity.
- Replace any probe which is malfunctioning or showing excessive or uneven wear.
- Remove the batteries from TG11 if you are not going to use it for a long time.



## **EASZ-TG11 SPECIFICATIONS**

Measurable Materials:	Steel, Cast Steel, Cast Iron, Aluminum, Other Metals, Hard plastics, Glass, Ceramics
Measuring Range:	0.04" to 11.8" (1 to 300mm)
Probe:	Dual Crystal Transmit/Receive Type
Key Pad:	Sealed Tactile Response
Velocity:	39,300 to 393,700 inches/sec. (1000 to 9999 m/sec,)
Display:	4 digit LCD
Resolution:	0.004" (0.1mm)
Accuracy:	± 0.004" (below 2.5") ± 0.3% (above 2.5") or ± (0.1mm below 60mm, ± 0.3% above 60mm)
V path Correction:	Built-In for improved accuracy
Calibration:	One Step Calibration
Battery:	Two AA Dry Cells or NiCad
Operating Time:	Up to 20 hours with Alkaline cells
Low Battery:	Blinking LCD for ½ hour
Auto Power Off:	3 minute delay
Size:	5" (H) X 2.5"(W) X 1.2"(T) (125mm X 65mm X 30mm)
Weight:	7 ounces with batteries (200 grams with batteries)
Housing:	ABS molded Plastic

## **NOTES**



#### Please direct all questions to:



EESiFlo Inc.

219 East Main Street Mechanicsburg, PA, 17055

Toll-Free Phone: (866) EESIFLO (866-337-4356)

or: (717) 697-8546 Fax: (717) 697-2122 Email: Sales@EESiFlo.US